Form 10-300 (Rev. 6-72)		ES DEPARTMENT	OF THE INTERIOR	Ī	STATE:		
(((2), 0-)1)		TTORAL FARK SE	RVICE	-	Virgínia		······································
4	ATIONAL RE	GISTER OF H	ISTORIC PLA	CES	Brunswick		
	INVENTO	RÝ – NOMINA	TION FORM		FOR NPS L	JSE ONLY.	-
	( <b>T</b> )				ENTRY DATE		
· · · · · · · · · · · · · · · · · · ·	(Type all entrie	s - complete a	pplicable sectio	ns)			
L. NAME							
	field		-	•			
AND/OR HI	BARRY V					- <b>.</b>	
Melr	ose						
2. LOCATION	STATUS AND AND AND A STATUS AND			, v 0.00			
1	NUMBER:	and the second		D		٥	
CITY OR TO	MILLES SOUTHE	east of inte	ersection of	CONGRESSIO	6 and Route 5	0	
	eville vicir	nity		Fifth (	W, C. Daniel)		`
STATE			CODE	COUNTY			CODE
Virgini 3. CLASSIFIC			51	Brunswi	ck	· · · · · · · · · · · ·	025
	TEGORY	45.45.25.1 •				ACCES	
	hock One)		OWNERSHIP		STATUS	TO THE	
District	X Building	D Public	Public Acquisit	ion:	Occupied	Yes:	
Site	Structure	X Private	In Pro		X Unaccupied	· 🕅 Restri	
	Object	Both .	Being	Considered	Preservation wa	rk □ No	micied
		1			in progress		
	SE (Check One or !		· · · · · · · · · · · · · · · · · · ·				
[] Agricult	ural C	overnment	Pork .		Transportation		nts
	ural C tial In	overnment dustrial	<ul> <li>Pork</li> <li>Private Reside</li> </ul>	nce (			nts
Agricult	ural C tial In ponal A	overnment idustrial ilitaty	Pork .	nce (	Transportation		nts 
Commerce Commerce Educati Entertai	ural C Sial In Sonal M Noment M PROPERTY	overnment idustrial ilitaty	<ul> <li>Pork</li> <li>Private Reside</li> <li>Religious</li> </ul>	nce (	Transportation		nts
Commerce Education Entertai	ural C Sial In Sonal M Noment M PROPERTY	overnment idustrial ilitaty	<ul> <li>Pork</li> <li>Private Reside</li> <li>Religious</li> </ul>	nce (	Transportation		
Agricult Commerce Education Entertain OWNER OF OWNER'S N The	ural C ial In onal M PROZERTY AME- Reverend Rob	overnment idustrial ilitary useum	<ul> <li>Pork</li> <li>Private Reside</li> <li>Religious</li> <li>Scientific</li> </ul>	nce (	Transportation		
Agricult Commerce Educati Entertai	ural C Gal In Sonal M RROPERTY AME Reverend Rob D NUMBER:	overnment ndustrial ilitary useum Dert S. Crea	<ul> <li>Pork</li> <li>Private Reside</li> <li>Religious</li> <li>Scientific</li> <li>mer, Jr.</li> </ul>	nce (	Transportation		
Agricult Commerce Educati Entertai	ural C Gal In Sonal M PROZERTY AME Reverend Rob D NUMBER: Rectory, Sai	overnment ndustrial ilitary useum Dert S. Crea	<ul> <li>Pork</li> <li>Private Reside</li> <li>Religious</li> <li>Scientific</li> <li>mer, Jr.</li> </ul>	nce (	Transportation		Virginia DF
Agricult Commerce Educati Entertai OWNER OF OWNER'S N The STREET AN The CITY OR TO	ural C Gal In Sonal M PROZERTY AME Reverend Rob D NUMBER: Rectory, Sai	overnment ndustrial ilitary useum Dert S. Crea	<ul> <li>Pork</li> <li>Private Reside</li> <li>Religious</li> <li>Scientific</li> <li>mer, Jr.</li> </ul>	Thurch	Transportation		Virginia
Agricult Commerce Educati Entertai OWNER OF OWNER'S N The STREET AN The CITY OR TO Lawr 3. LOCATION	ural C ial In onal M nment M RROZERTY AME. Reverend Rob D NUMBER: Rectory, Sai WN: enceville OF LEGAL DESC	overnment idustrial ilitary useum pert S. Crea int Andrew's RIPTION	<ul> <li>Pork</li> <li>Private Reside</li> <li>Religious</li> <li>Scientific</li> <li>mer, Jr.</li> </ul>	Thurch	Transportation. Transportation. Other (Specify) eing restored	Comme:	Virginia
Agricult     Agricult     Commerce     Educati     Entertai      Agricult     Entertai      Agricult     Entertai      Agricult     Entertai      The     STREET AN     The     CITY OR TC     Lawr      LOCATION     COURTHOUS	ural C Gal In Sonal M Ament M RROZERTY AME. Reverend Rob D NUMBER: Rectory, Sai WN: enceville OF LEGAL DESC GF LEGAL DESC	overnment idustrial ilitary useum pert S. Crea int Andrew's CRIPTION DEEDS. ETC:	<ul> <li>Pork</li> <li>Private Reside</li> <li>Religious</li> <li>Scientific</li> <li>mer, Jr.</li> <li>Episcopal (</li> </ul>	Thurch	Transportation. Transportation. Other (Specify) eing restored	Comme:	Virginia DF 1
Agricult     Commerce     Educati     Entertai      OWNER OF     OWNER'S N     The     STREET AN     The     CITY OR TO     Lawr      LOCATION     COURTHOUS	ural G G G G G G G G G G G G G G G G G G G	overnment idustrial ilitary useum pert S. Crea int Andrew's CRIPTION DEEDS. ETC:	<ul> <li>Pork</li> <li>Private Reside</li> <li>Religious</li> <li>Scientific</li> <li>mer, Jr.</li> <li>Episcopal (</li> </ul>	Thurch	Transportation. Transportation. Other (Specify) eing restored	Comme:	Virginia DF 1
Agricult     Agricult     Commerce     Educati     Entertai      OWNER OF     OWNER'S N     The     STREET AN     CITY OR TC     Lawr     STREET AN     STREET AN	ural G Gal In Sial In Sonal M Mennent M RROPERTY AME: Reverend Rob D NUMBER: Rectory, Sai WN: enceville DF LEGAL DESC SE, REGISTRY OF I SWick County D NUMBER:	overnment idustrial ilitary useum pert S. Crea nt Andrew's RIPTION DEEDS. ETC: r Court Hous	<ul> <li>Pork</li> <li>Private Reside</li> <li>Religious</li> <li>Scientific</li> <li>mer, Jr.</li> <li>Episcopal (</li> </ul>	Thurch	Transportation. Transportation. Other (Specify) eing restored	Comme:	Virginia DF 1
Agricult     Commerce     Educati     Entertai      OWNER OF     OWNER'S N     The     STREET AN     CITY OR TC     Lawr      LOCATION     STREET AN     STREET AN	ural G Gal In Sial In Sial In Sonal I M M PROPERTY AME: Reverend Rob NUMBER: Rectory, Sai WN: enceville OF LEGAL DESC SE, REGISTRY OF IN SWICK County D NUMBER: d book 37, p	overnment idustrial ilitary useum pert S. Crea nt Andrew's RIPTION DEEDS. ETC: r Court Hous	<ul> <li>Pork</li> <li>Private Reside</li> <li>Religious</li> <li>Scientific</li> <li>mer, Jr.</li> <li>Episcopal (</li> </ul>	Thurch	Transportation. Transportation. Other (Specify) eing restored	Сотте: 	Virginia
Agricult     Agricult     Commerce     Educati     Entertai      Anner of     The     STREET AN     COURTHOUS     STREET AN     COURTHOUS     Brun     STREET AN     (De'e     GITY OR TO	ural G G G G G G G G G C C C C C C C C C C C C C	overnment idustrial ilitary useum pert S. Crea nt Andrew's RIPTION DEEDS. ETC: r Court Hous	<ul> <li>Pork</li> <li>Private Reside</li> <li>Religious</li> <li>Scientific</li> <li>mer, Jr.</li> <li>Episcopal (</li> </ul>	Church STATE STATE	Transportation. Transportation. Tother (specity) eing restored inia 23868	Comme:	Virginia Brunswick
CITY OR TO COURTHOUS COURT OF CITY OR TO COURT OF CITY OR TO COURT OF COURT	ural G G G G G G G G G G G G G G G G G G G	overnment idustrial ili:ary useum pert S. Crea int Andrew's CRIPTION DEEDS, ETC: COURT HOUS 0. 266.)	<ul> <li>Pork</li> <li>Private Reside</li> <li>Religious</li> <li>Scientific</li> <li>mer, Jr.</li> <li>Episcopal (</li> </ul>	Church STATE STATE	Transportation. Transportation. Other (Specify) eing restored	Comme:	Virginia Brunswick
CITY OR TO COURTHOUS COURTHOUS COURT OF CITY OR TO COURTHOUS COURT	ural G G G G G G G G G G G G G G G G G G G	overnment idustrial ili:ary useum pert S. Crea int Andrew's CRIPTION DEEDS, ETC: COURT HOUS 0. 266.)	<ul> <li>Pork</li> <li>Private Reside</li> <li>Religious</li> <li>Scientific</li> <li>mer, Jr.</li> <li>Episcopal (</li> </ul>	Church STATE STATE	Transportation. Transportation. Tother (specity) eing restored inia 23868	Comme:	Virginia Brunswick
Agricult     Agricult     Commerce     Educati     Entertai      OWNER OF     OWNER'S N     The     STREET AN     CITY OR TC     Lawr     COURTHOUS     Brun     STREET AN     (Dee     CITY OR TO     Lawr      CITY OR TO     Lawr      CITY OR TO     Lawr      TILE OF S	ural G Gal In Sial In Sial In Sonal M M PROPERTY AME: Reverend Rob D NUMBER: Rectory, Sai WN: enceville D NUMBER: d book 37, p WN: enceville TATION IN EXIST URVEY:	overnment idustrial illiary useum pert S. Crea nt Andrew's RIPTION DEEDS.ETC: COURT HOUS 266.) TING SURVEYS	Pork Private Reside Religious Scientific mer, Jr. Episcopal (	Thurch STATE: Virg	Transportation. Transportation. Tother (specity) eing restored inia 23868	Comme:	Virginia Brunswick
Agricult     Compared     Educati     Educati     Entertai      OWNER OF      OWNER'S N      The      STREET AN      CITY OR TO      Lawr      STREET AN      (Dee      CITY OR TO      Lawr      STREET AN      (Dee      CITY OR TO      Lawr      STREET AN      (Dee      CITY OR TO      Lawr      STRESEN      TITLE OF S      Virg      DATE OF SL	ural G G G G G G G G G G C C C C C C C C C C C C C	overnment idustrial ili:ary useum pert S. Crea int Andrew's CRIPTION DEEDS. ETC: COURT HOUS D. 266.) FING SURVEYS c Landmarks	Pork Private Reside Religious Scientific mer, Jr. Episcopal (	Thurch STATE: Virg	□ Transportation. ∑ Other (specify) eing restored 	Comme:	Virginia Brunswick
Agricult     Agricult     Commerce     Educati     Entertai      OWNER OF     OWNER'S N     The     STREET AN     The     CITY OR TO     Lawr      COURTHOUS     Brun     STREET AN     (Dee     CITY OR TO     Lawr      STREETAN     (Dee     (Streetan	ural G G G G G G G G G G G G G G G G G G G	overnment idustrial illiary useum pert S. Crea int Andrew's CRIPTION DEEDS, ETC: COURT HOUS D. 266.) TING SURVEYS IC Landmarks CORDS:	Pork Private Reside Religious Scientific mer, Jr. Episcopal ( a Commission Federal	Survey	□ Transportation. ∑ Other (specify) eing restored 	Comme:	Virginia Brunswick
CITY OR TO COURTHOUS COURT	ural G G G G G G G G G G G G C C C C C C C C C C C C C	overnment idustrial illiary useum pert S. Crea int Andrew's CRIPTION DEEDS, ETC: COURT HOUS D. 266.) TING SURVEYS IC Landmarks CORDS:	Pork Private Reside Religious Scientific mer, Jr. Episcopal ( a Commission Federal	Survey	□ Transportation. ∑ Other (specify) eing restored 	Comme:	Virginia Brunswick
Agricult     Commerce     Educati     Entertai      OWNER'S N      The     STREET AN      CITY OR TO     Lawr      LOCATION      STREET AN      (Dee     CITY OR TO      Lawr      STREET AN      TITLE OF S      Virg     DATE OF SL      DEPOSITOR      Virg      STREET AN	ural G G G G G G G G G G G G G G G G G G G	overnment idustrial illitary useum Dert S. Crea int Andrew's RIPTION DEEDS.ETC: COURT HOUS COURT HOUS COURT HOUS CLANDMARKS CLANDMARKS	Pork Private Reside Religious Scientific mer, Jr. Episcopal ( a Commission Federal	Survey	□ Transportation. ∑ Other (specify) eing restored 	Comme:	Virginia Brunswick
Agricult     Commerce     Educati     Entertai      OWNER'S N      The     STREET AN      CITY OR TO     Lawr      LOCATION      STREET AN      (Dee     CITY OR TO      Lawr      STREET AN      TITLE OF S      Virg     DATE OF SL      DEPOSITOR      Virg      STREET AN	ural G G G G G G G G G G G G G G G G G G G	overnment idustrial illitary useum Dert S. Crea int Andrew's RIPTION DEEDS.ETC: COURT HOUS COURT HOUS COURT HOUS CLANDMARKS CLANDMARKS	Pork Private Reside Religious Scientific mer, Jr. Episcopal ( a Commission Federal	Survey	□ Transportation. ∑ Other (specify) eing restored 	Comme:	Virginia Brunswick

CONDITION         Excellent         2 Good         Fail         Distribution         Reins         Undergoard           CONDITION         Excellent         2 Altreet         B Undergoard         (Check One)           Condition         Control of the co	DESCRIPTION	
Condition Charter one charter of the second		
(Check One)     (Check On	CONDITION	🗍 Excellent 🕱 Good 🗌 Fair 🗋 Dateriarated 🗍 Ruins 🗌 Unexposed
<ul> <li>A. General Statement: <ol> <li>B. Bentfield, constructed in 1810, comprises one of the principle manor houses and plantation groups not only in Brunswick County, but in all of Southside Virginia. The number, general location and arrangement of the buildings and gardens makes Bentfield a significant example of federal plantation architecture of the early nineteenth century. The interior wood paneling is elegancily refined.</li> <li>Condition of fabric: Good, and in the process of restoration.</li> <li>B. Description of the Interior: <ol> <li>The main body of the house is a large, single pile seven bay brick structure, two-and-one-half stories high. A wooden kitchen wing was attached to the facade's central three bays probably in the mid-nineteenth century. The rear of the structure, facing away from the Meherrin River, became the principle facade.</li> <li>Foundations: brick.</li> <li>Wall construction, finish and color: Exceptionally fine Flemish bond brickwork with molded brick water table. Pullog holes are found on both sides of each window and two are found on each side of the chimney stacks, with one in the center of each stack.</li> <li>Structural system, framing: Brick interior and exterior bearing walls. Interior wood framing.</li> <li>Chimneys: There are two, high exterior chimney stacks, one on the east wall and one on the west wall. Each stack splays inward at the cornice line.</li> <li>Openings:         <ol> <li>Doways and doors: There are two entrances to the main structure, both through the center bays of the north and south facades. Each structure, both through the center bays of the north and south facades.</li> <li>Nindows and shutters: All of the windows are wooden double-hung nine-over-nine sash with flar rubbed brick arches. Many of the original shutters remain with double paneled howable vents.</li> <li>Roof: A gable roof covered with tin, with a plain box cornice.</li> </ol> </li> <li>D. Second floor: The stair leads to the sacult ding noom with fireplace. To the west of the shall</li></ol></li></ol></li></ul>		
<ul> <li>A. General Statement: <ol> <li>Bentfield, constructed in 1810, comprises one of the principle manor houses and plantation groups not only in Brunswick County, but in all of Southside Virginia. The number, general location and arrangement of the buildings and gardems makes Bentfield a significant example of federal plantation architecture of the early nineteenth century. The interior wood paneling is elegantly refined.</li> <li>Condition of fabric: Good, and in the process of restoration.</li> </ol></li></ul> B. Description of the Interior: <ol> <li>The main body of the house is a large, single pile seven bay brick structure, two-and-one-half stories high. A wooden kitchen wing was attached to the facade's central three bays probably in the mid-nineteenth century. The rear of the structure, facing away from the Meherrin River, became the principle facade.</li> <li>Foundations: brick.</li> <li>Wall construction, finish and color: Exceptionally fine flucts of each window and two are found on each side of the chinney stacks, with one in the center of each stack.</li> <li>A. Structural system, framing: Brick interior and exterior bearing walls. Interior wood framing.</li> <li>Chinneys: There are two, high exterior chinney stacks, one on the east wall and one on the west wall. Each stack splays inward at the cornice line.</li> <li>Openings:     <ul> <li>a. Doorways and doors: There are two entrances to the main structure, both through the center bays of the north and south facades. Each consists of a double raised three paneled door with banded wooden surrounds.</li> </ul></li></ol> <li>Theor plans:     <ul> <li>a. First floor: The entrance from the south side of the structure opens into a large rectangular hall with a partially enclosed star in the northwest corner of the room. To the east of the hall is a large parlow with fireplace.</li> </ul> </li>		
<ol> <li>Bentfield, constructed in 1810, comprises one of the principle manor houses and plantation groups not only in Brunswick County, but in all of Southside Virginia. The number, general location and arrangement of the buildings and gardens makes Bentfield a significant example of federal plantation architecture of the early nineteenth century. The interior wood paneling is elegantly refined.</li> <li>Condition of fabric: Cood, and in the process of restoration.</li> <li>Description of the Interior:         <ol> <li>The main body of the house is a large, single pile seven bay brick structure, two-and-one-balf stories high. A wooden kitchen wing was attached to the facade's central three bays probably in the mid-rin River, became the principle facade.</li> <li>Foundations: brick.</li> <li>Wall construction, finish and color: Exceptionally fine Flemish bond brickwork with molded brick water table. Rutlog holes are found on both sides of each window and two are found on each side of the chinney stacks, with one in the center of each stack.</li> <li>Station of the raises and doors: There are two entrances to the main structure, both through the center bays of the north and south facades. Each consists of a double raised three paneled door with bande wooden surrounds. The flat archivolts are of rubbed bricks.</li> <li>Modows and shutters: All of the windows are wooden double- hung nine-over-nine sesh with flat rubbed brick arches. Many of the original shutters remain with double paneled movable vents.</li> <li>Roor: A gable roof covered with tin, with a plain box coroice.</li> </ol> </li> <li>Description of Interior:         <ol> <li>Floor plans:</li></ol></li></ol>	DESCRIBE THE PR	RESENT AND ORIGINAL (If known) PHYSICAL APPEARANCE
<pre>manor houses and plantation groups not only in Brunswick County, but in all of Southside Virginia. The number, general location and arrangement of the buildings and gardens makes Bentfield a significant example of federal plantation architecture of the early nineteenth century. The interior wood paneling is elegantly refined. 2. Condition of fabric: Good, and in the process of restoration. B. Description of the Interior: 1. The main body of the house is a large, single pile seven bay brick structure, two-and-one-half stories high. A wooden kitchen wing was attached to the facade's central three bays probably in the mid-nineteenth century. The rear of the structure, facing away from the Meherrin River, became the principle facade. 2. Foundations: brick. 3. Wall construction, finish and color: Exceptionally fine Flemish bond brickwork with molded brick water table. Putlog holes are found on both sides of each window and two are found on each side of the chimney stacks, with one in the center of each stack. 4. Structural system, framing: Brick interior and exterior bearing walls. Interior wood framing. 5. Chimneys: There are two, high exterior chimney stacks, one on the east wall and one on the west wall. Each stack splays inward at the cornice line. 6. Openings: a. Doorways and doors: There are two entrances to the main structure, both through the center bays of the north and south facades. Each consists of a double raised three paneled door with banded wooden surrounds. The flat archivolts are of rubbed bricks. b. Windows and shutters: All of the windows are wooden doubla- hung nine-over-nine sash with flat rubbed brick arches. Many of the original shutters remain with double paneled movale wents. 7. Roof: A gable roof covered with tin, with a plain box cornice. C. Description of Interior: 1. Floor plans: a. First floor: The entrance from the south side of the structure opens into a large rectangular hall with a partially enclosed stair is the northwest corner of the roow. To the east of the hall is a large</pre>		
<ol> <li>The main body of the house is a large, single pile seven bay brick structure, two-and-one-half stories high. A wooden kitchen wing was attached to the facade's central three bays probably in the mid-nineteenth century. The rear of the structure, facing away from the Meherrin River, became the principle facade.         <ol> <li>Foundations: brick.</li> <li>Wall construction, finish and color: Exceptionally fine Flemish bond brickwork with molded brick water table. Putlog holes are found on both sides of each window and two are found on each side of the chinney stacks, with one in the center of each stack.</li></ol></li></ol>	manor house of Southsie buildings a plantation paneling is	es and plantation groups not only in Brunswick County, but in all de Virginia. The number, general location and arrangement of the and gardens makes Bentfield a significant example of federal architecture of the early nineteenth century. The interior wood s elegantly refined.
<ol> <li>The main body of the house is a large, single pile seven bay brick structure, two-and-one-half stories high. A wooden kitchen wing was attached to the facade's central three bays probably in the mid-nineteenth century. The rear of the structure, facing away from the Meherrin River, became the principle facade.         <ol> <li>Foundations: brick.</li> <li>Wall construction, finish and color: Exceptionally fine Flemish bond brickwork with molded brick water table. Putlog holes are found on both sides of each window and two are found on each side of the chinney stacks, with one in the center of each stack.</li></ol></li></ol>	B. Descrip	ption of the Interior:
<pre>attached to the facade's central three bays probably in the mid-nineteenth century. The rear of the structure, facing away from the Meherrin River, became the principle facade. 2. Foundations: brick. 3. Wall construction, finish and color: Exceptionally fine Flemish bond brickwork with molded brick water table. Putlog holes are found on both sides of each window and two are found on each side of the chimney stacks, with one in the center of each stack. 4. Structural system, framing: Brick interior and exterior bearing walls. Interior wood framing. 5. Chimneys: There are two, high exterior chimney stacks, one on the east wall and one on the west wall. Each stack splays inward at the cornice line. 6. Openings: a. Doorways and doors: There are two entrances to the main structure, both through the center bays of the north and south facades. Each consists of a double raised three paneled door with banded wooden surrounds. The flat archivolts are of rubbed bricks. b. Windows and shutters: All of the windows are wooden double- hung nine-over-nine sash with flat rubbed brick arches. Many of the original shutters remain with double paneled movable vents. 7. Roof: A gable roof covered with tin, with a plain box cornice. C. Description of Interior: 1. Floor plans: a. Pirst floor: The entrance from the south side of the structure opens into a large rectangular hall with a partially enclosed stair in the northwest corner of the room. To the east of the hall is a large parlor with fireplace. b. Second floor: The stair leads to the second floor front hall. To the west of the stair is a large bedroom with fireplace and two storage areas at the rear of the house. Two bedrooms lie to the north of the second floor front hall, while the master bedroom with fireplace is found at the end of the hall in the extreme eastern end of the structure. 2. Stairway: The mahogany stair is located in a high stair-hall which runs perpendicular to the south facade of the structure. The stair</pre>	-	
<ul> <li>became the principle facade.</li> <li>2. Foundations: brick.</li> <li>3. Wall construction, finish and color: Exceptionally fine</li> <li>Flemish bond brickwork with molded brick water table. Putlog holes are found on both sides of each window and two are found on each side of the chimey stacks, with one in the center of each stack.</li> <li>4. Structural system, framing: Brick interior and exterior bearing walls. Interior wood framing.</li> <li>5. Chimneys: There are two, high exterior chimney stacks, one on the east wall and one on the west wall. Each stack splays inward at the cornice line.</li> <li>6. Openings: <ul> <li>a. Doorways and doors: There are two entrances to the main structure, both through the center bays of the north and south facades. Each consists of a double raised three paneled door with banded wooden surrounds. The flat archivolts are of rubbed bricks.</li> <li>b. Windows and shutters: All of the windows are wooden double-hung nine-over-nine sash with flat rubbed brick arches. Many of the original shutters remain with double paneled movable vents.</li> <li>7. Roof: A gable roof covered with tin, with a plain box cornice.</li> </ul> </li> <li>C. Description of Interior: <ul> <li>a. First floor: The entrance from the south side of the structure opens into a large rectangular hall with a partially enclosed stair in the northwest corner of the room. To the east of the hall is a large parlor with fireplace.</li> <li>b. Second floor: The stair leads to the second floor front hall. To the west of the stair is a large bedroom with fireplace and two storage areas at the rear of the house. Two bedrooms lie to the north of the second floor front hall, while the master bedroom with fireplace is found at the end of the hall in the extreme eastern end of the structure.</li> </ul></li></ul>		
<ol> <li>Foundations: brick.         <ol> <li>Wall construction, finish and color: Exceptionally fine</li> </ol> </li> <li>Flemish bond brickwork with molded brick water table. Putlog holes are found on both sides of each window and two are found on each side of the chimney stacks, with one in the center of each stack.</li></ol>		
<ul> <li>3. Wall construction, finish and color: Exceptionally fine Flemish bond brickwork with molded brick water table. Putlog holes are found on both sides of each window and two are found on each side of the chimney stacks, with one in the center of each stack. <ul> <li>4. Structural system, framing: Brick interior and exterior</li> <li>bearing walls. Interior wood framing.</li> <li>5. Chimneys: There are two, high exterior chimney stacks, one on the east wall and one on the west wall. Each stack splays inward at the cornice line. <ul> <li>6. Openings:</li> <li>a. Doorways and doors: There are two entrances to the main structure, both through the center bays of the north and south facades. Each consists of a double raised three paneled door with banded wooden surrounds. The flat archivolts are of rubbed bricks. <ul> <li>b. Windows and shutters: All of the windows are wooden double- hung nine-over-nine sash with flat rubbed brick arches. Many of the original shutters remain with double paneled movable vents. <ul> <li>7. Roof: A gable roof covered with tin, with a plain box cornice.</li> </ul> </li> </ul> </li> <li>C. Description of Interior: <ul> <li>a. First floor; The entrance from the south side of the structure opens into a large rectangular hall with a partially enclosed stair in the northwest corner of the room. To the east of the hall is a large parlor with fireplace. To the west of the hall is a smaller dining room with fireplace. <ul> <li>b. Second floor: The stair leads to the second floor front hall. To the west of the house. Two bedrooms lie to the north of the second floor front hall, while the master bedroom with fireplace is found at the end of the hall in the extreme eastern end of the structure. <ul> <li>2. Stairway: The mahogany stair is located in a high stait-hall which runs perpendicular to the south facade of the structure.</li> </ul> </li> </ul></li></ul></li></ul></li></ul></li></ul>	became the	principle facade.
<pre>Flemish bond brickwork with molded brick water table. Putlog holes are found on both sides of each window and two are found on each side of the chimney stacks, with one in the center of each stack.</pre>	2	2. Foundations: brick.
<pre>found on both sides of each window and two are found on each side of the chimney stacks, with one in the center of each stack.</pre>		3. Wall construction, finish and color: Exceptionally fine
<pre>found on both sides of each window and two are found on each side of the chimney stacks, with one in the center of each stack.</pre>		
<ul> <li>4. Structural system, framing: Brick interior and exterior bearing walls. Interior wood framing. <ol> <li>Chinneys: There are two, high exterior chinney stacks, one on the east wall and one on the west wall. Each stack splays inward at the cornice line.</li> <li>Openings: <ol> <li>Dorways and doors: There are two entrances to the main structure, both through the center bays of the north and south facades. Each consists of a double raised three paneled door with banded wooden surrounds. The flat archivolts are of rubbed bricks.</li> <li>Windows and shutters: All of the windows are wooden double-hung nine-over-nine sash with flat rubbed brick arches. Many of the original shutters remain with double paneled movable vents.</li> <li>Roof: A gable roof covered with tin, with a plain box cornice.</li> </ol> </li> <li>C. Description of Interior: <ol> <li>Floor plans:</li> <li>Barge parlor with fireplace. To the west of the hall is a smaller dining room with fireplace.</li> <li>Second floor: The stair leads to the second floor front hall. To the west of the stair is a large bedroom with fireplace and two storage areas at the rear of the house. Two bedrooms lie to the north of the second floor front hall, while the master bedroom with fireplace is found at the end of the hall in the extreme eastern end of the stair-hall which runs perpendicular to the south facade of the stair</li> </ol> </li> </ol></li></ul>		
<ul> <li>4. Structural system, framing: Brick interior and exterior bearing walls. Interior wood framing. <ol> <li>Chinneys: There are two, high exterior chinney stacks, one on the east wall and one on the west wall. Each stack splays inward at the cornice line.</li> <li>Openings: <ol> <li>Dorways and doors: There are two entrances to the main structure, both through the center bays of the north and south facades. Each consists of a double raised three paneled door with banded wooden surrounds. The flat archivolts are of rubbed bricks.</li> <li>Windows and shutters: All of the windows are wooden double-hung nine-over-nine sash with flat rubbed brick arches. Many of the original shutters remain with double paneled movable vents.</li> <li>Roof: A gable roof covered with tin, with a plain box cornice.</li> </ol> </li> <li>C. Description of Interior: <ol> <li>Floor plans:</li> <li>Barge parlor with fireplace. To the west of the hall is a smaller dining room with fireplace.</li> <li>Second floor: The stair leads to the second floor front hall. To the west of the stair is a large bedroom with fireplace and two storage areas at the rear of the house. Two bedrooms lie to the north of the second floor front hall, while the master bedroom with fireplace is found at the end of the hall in the extreme eastern end of the stair-hall which runs perpendicular to the south facade of the stair</li> </ol> </li> </ol></li></ul>	chimney sta	acks, with one in the center of each stack.
<pre>bearing walls. Interior wood framing. 5. Chimneys: There are two, high exterior chimney stacks, one on the east wall and one on the west wall. Each stack splays inward at the cornice line. 6. Openings: a. Doorways and doors: There are two entrances to the main structure, both through the center bays of the north and south facades. Each consists of a double raised three paneled door with banded wooden surrounds. The flat archivolts are of rubbed bricks. b. Windows and shutters: All of the windows are wooden double- hung nine-over-nine sash with flat rubbed brick arches. Many of the original shutters remain with double paneled movable vents. 7. Roof: A gable roof covered with tin, with a plain box cornice. C. Description of Interior: 1. Floor plans: a. First floor: The entrance from the south side of the structure opens into a large rectangular hall with a partially enclosed stair in the northwest corner of the room. To the east of the hall is a large parlor with fireplace. b. Second floor: The stair leads to the second floor front hall. To the west of the stair is a large bedroom with fireplace and two storage areas at the rear of the house. Two bedrooms lie to the north of the second floor front hall, while the master bedroom with fireplace is found at the end of the hall in the extreme eastern end of the structure. 2. Stairway: The mahogany stair is located in a high stair-hall which runs perpendicular to the south facade of the structure. The stair</pre>		
<ul> <li>5. Chimneys: There are two, high exterior chimney stacks, one on the east wall and one on the west wall. Each stack splays inward at the cornice line. <ul> <li>6. Openings:</li> <li>a. Doorways and doors: There are two entrances to the main structure, both through the center bays of the north and south facades. Each consists of a double raised three paneled door with banded wooden surrounds. The flat archivolts are of rubbed bricks.</li> <li>b. Windows and shutters: All of the windows are wooden double hung nine-over-nine sash with flat rubbed brick arches. Many of the original shutters remain with double paneled movable vents.</li> <li>7. Roof: A gable roof covered with tin, with a plain box cornice.</li> </ul> </li> <li>C. Description of Interior: <ul> <li>I. Floor plans:</li> <li>a. First floor: The entrance from the south side of the structure opens into a large rectangular hall with a partially enclosed stair in the northwest corner of the room. To the east of the hall is a large parlor with fireplace. To the west of the hall is a smaller dining room with fireplace.</li> <li>b. Second floor: The stair leads to the second floor front hall. To the west of the stair is a large bedroom with fireplace and two storage areas at the rear of the house. Two bedrooms lie to the north of the second floor front hall, while the master bedroom with fireplace is found at the end of the hall in the extreme eastern end of the structure.</li> </ul> </li> </ul>		
<pre>on the east wall and one on the west wall. Each stack splays inward at the cornice line. 6. Openings: a. Doorways and doors: There are two entrances to the main structure, both through the center bays of the north and south facades. Each consists of a double raised three paneled door with banded wooden surrounds. The flat archivolts are of rubbed bricks. b. Windows and shutters: All of the windows are wooden double- hung nine-over-nine sash with flat rubbed brick arches. Many of the original shutters remain with double paneled movable vents. 7. Roof: A gable roof covered with tin, with a plain box cornice. C. Description of Interior: 1. Floor plans: a. First floor; The entrance from the south side of the structure opens into a large rectangular hall with a partially enclosed stair in the northwest corner of the room. To the east of the hall is a large parlor with fireplace. b. Second floor: The stair leads to the second floor front hall. To the west of the stair is a large bedroom with fireplace and two storage areas at the rear of the house. Two bedrooms lie to the north of the second floor front hall, while the master bedroom with fireplace is found at the end of the hall in the extreme eastern end of the structure. 2. Stairway: The mahogany stair is located in a high stair-hall which runs perpendicular to the south facade of the structure. The stair</pre>		
<pre>the cornice line. 6. Openings: a. Doorways and doors: There are two entrances to the main structure, both through the center bays of the north and south facades. Each consists of a double raised three paneled door with banded wooden surrounds. The flat archivolts are of rubbed bricks. b. Windows and shutters: All of the windows are wooden double- hung nine-over-nine sash with flat rubbed brick arches. Many of the original shutters remain with double paneled movable vents. 7. Roof: A gable roof covered with tin, with a plain box cornice. C. Description of Interior: 1. Floor plans: a. First floor: The entrance from the south side of the structure opens into a large rectangular hall with a partially enclosed stair in the northwest corner of the room. To the east of the hall is a large parlor with fireplace. To the west of the hall is a smaller dining room with fireplace. b. Second floor: The stair leads to the second floor front hall. To the west of the stair is a large bedroom with fireplace and two storage areas at the rear of the house. Two bedrooms lie to the north of the second floor front hall, while the master bedroom with fireplace is found at the end of the hall in the extreme eastern end of the structure. 2. Stairway: The mahogany stair is located in a high stair-hall which runs perpendicular to the south facade of the structure. The stair</pre>		
<ul> <li>6. Openings: <ul> <li>a. Doorways and doors: There are two entrances to the main structure, both through the center bays of the north and south facades. Each consists of a double raised three paneled door with banded wooden surrounds. The flat archivolts are of rubbed bricks.</li> <li>b. Windows and shutters: All of the windows are wooden double-hung nine-over-nine sash with flat rubbed brick arches. Many of the original shutters remain with double paneled movable vents.</li> <li>7. Roof: A gable roof covered with tin, with a plain box cornice.</li> </ul> </li> <li>C. Description of Interior: <ul> <li>a. First floor: The entrance from the south side of the structure opens into a large rectangular hall with a partially enclosed stair in the northwest corner of the room. To the east of the hall is a large parlor with fireplace. To the west of the hall is a smaller dining room with fireplace.</li> <li>b. Second floor: The stair leads to the second floor front hall. To the west of the house. Two bedrooms lie to the north of the second floor front hall, while the master bedroom with fireplace is found at the end of the hall in the extreme eastern end of the structure.</li> <li>2. Stairway: The mahogany stair is located in a high stair-hall which runs perpendicular to the south facade of the structure. The stair</li> </ul> </li> </ul>		
<ul> <li>a. Doorways and doors: There are two entrances to the main structure, both through the center bays of the north and south facades. Each consists of a double raised three paneled door with banded wooden surrounds. The flat archivolts are of rubbed bricks. <ul> <li>b. Windows and shutters: All of the windows are wooden double-hung nine-over-nine sash with flat rubbed brick arches. Many of the original shutters remain with double paneled movable vents.</li> <li>7. Roof: A gable roof covered with tin, with a plain box cornice.</li> </ul> </li> <li>C. Description of Interior: <ul> <li>a. First floor: The entrance from the south side of the structure opens into a large rectangular hall with a partially enclosed stair in the northwest corner of the room. To the east of the hall is a large parlor with fireplace.</li> <li>b. Second floor: The stair leads to the second floor front hall. To the west of the stair is a large bedroom with fireplace and two storage areas at the rear of the house. Two bedrooms lie to the north of the second floor front hall, while the master bedroom with fireplace is found at the end of the hall in the extreme eastern end of the structure.</li> <li>2. Stairway: The mahogany stair is located in a high stair-hall which runs perpendicular to the south facade of the structure. The stair</li> </ul> </li> </ul>		
<pre>structure, both through the center bays of the north and south facades. Each consists of a double raised three paneled door with banded wooden surrounds. The flat archivolts are of rubbed bricks.</pre>		
<pre>consists of a double raised three paneled door with banded wooden surrounds. The flat archivolts are of rubbed bricks.</pre>	structure,	
The flat archivolts are of rubbed bricks. b. Windows and shutters: All of the windows are wooden double- hung nine-over-nine sash with flat rubbed brick arches. Many of the original shutters remain with double paneled movable vents. 7. Roof: A gable roof covered with tin, with a plain box cornice. C. Description of Interior: 1. Floor plans: a. First floor: The entrance from the south side of the structure opens into a large rectangular hall with a partially enclosed stair in the northwest corner of the room. To the east of the hall is a large parlor with fireplace. To the west of the hall is a smaller dining room with fireplace. b. Second floor: The stair leads to the second floor front hall. To the west of the stair is a large bedroom with fireplace and two storage areas at the rear of the house. Two bedrooms lie to the north of the second floor front hall, while the master bedroom with fireplace is found at the end of the hall in the extreme eastern end of the structure. 2. Stairway: The mahogany stair is located in a high stair-hall which runs perpendicular to the south facade of the structure. The stair		
<ul> <li>b. Windows and shutters: All of the windows are wooden double- hung nine-over-nine sash with flat rubbed brick arches. Many of the original shutters remain with double paneled movable vents.</li> <li>7. Roof: A gable roof covered with tin, with a plain box cornice.</li> <li>C. Description of Interior: <ol> <li>Floor plans: <ol> <li>First floor: The entrance from the south side of the structure opens into a large rectangular hall with a partially enclosed stair in the northwest corner of the room. To the east of the hall is a large parlor with fireplace. To the west of the hall is a smaller dining room with fireplace.</li> <li>Second floor: The stair leads to the second floor front hall. To the west of the stair is a large bedroom with fireplace and two storage areas at the rear of the house. Two bedrooms lie to the north of the second floor front hall, while the master bedroom with fireplace is found at the end of the hall in the extreme eastern end of the structure.</li> <li>Stairway: The mahogany stair is located in a high stair-hall which runs perpendicular to the south facade of the structure. The stair</li> </ol> </li> </ol></li></ul>		
<pre>hung nine-over-nine sash with flat rubbed brick arches. Many of the original shutters remain with double paneled movable vents. 7. Roof: A gable roof covered with tin, with a plain box cornice. C. Description of Interior: 1. Floor plans: a. First floor: The entrance from the south side of the structure opens into a large rectangular hall with a partially enclosed stair in the northwest corner of the room. To the east of the hall is a large parlor with fireplace. To the west of the hall is a smaller dining room with fireplace. b. Second floor: The stair leads to the second floor front hall. To the west of the stair is a large bedroom with fireplace and two storage areas at the rear of the house. Two bedrooms lie to the north of the second floor front hall, while the master bedroom with fireplace is found at the end of the hall in the extreme eastern end of the structure. 2. Stairway: The mahogany stair is located in a high stair-hall which runs perpendicular to the south facade of the structure. The stair</pre>		
<pre>shutters remain with double paneled movable vents. 7. Roof: A gable roof covered with tin, with a plain box cornice. C. Description of Interior: 1. Floor plans: a. First floor: The entrance from the south side of the structure opens into a large rectangular hall with a partially enclosed stair in the northwest corner of the room. To the east of the hall is a large parlor with fireplace. To the west of the hall is a smaller dining room with fireplace. b. Second floor: The stair leads to the second floor front hall. To the west of the stair is a large bedroom with fireplace and two storage areas at the rear of the house. Two bedrooms lie to the north of the second floor front hall, while the master bedroom with fireplace is found at the end of the hall in the extreme eastern end of the structure. 2. Stairway: The mahogany stair is located in a high stair-hall which runs perpendicular to the south facade of the structure. The stair</pre>	hung nine-c	over-nine sash with flat rubbed brick arches. Many of the original
7. Roof: A gable roof covered with tin, with a plain box cornice. C. Description of Interior: <ul> <li>I. Floor plans:</li> <li>a. First floor: The entrance from the south side of the structure opens into a large rectangular hall with a partially enclosed stair in the northwest corner of the room. To the east of the hall is a large parlor with fireplace. To the west of the hall is a smaller dining room with fireplace.</li> <li>b. Second floor: The stair leads to the second floor front hall. To the west of the house. Two bedrooms lie to the north of the second floor front hall, while the master bedroom with fireplace is found at the end of the hall in the extreme eastern end of the stair-hall which runs perpendicular to the south facade of the structure. The stair</li> </ul>		
C. Description of Interior: 1. Floor plans: a. First floor: The entrance from the south side of the structure opens into a large rectangular hall with a partially enclosed stair in the northwest corner of the room. To the east of the hall is a large parlor with fireplace. To the west of the hall is a smaller dining room with fireplace. b. Second floor: The stair leads to the second floor front hall. To the west of the stair is a large bedroom with fireplace and two storage areas at the rear of the house. Two bedrooms lie to the north of the second floor front hall, while the master bedroom with fireplace is found at the end of the hall in the extreme eastern end of the structure. 2. Stairway: The mahogany stair is located in a high stair-hall which runs perpendicular to the south facade of the structure. The stair		
1. Floor plans: a. First floor: The entrance from the south side of the structure opens into a large rectangular hall with a partially enclosed stair in the northwest corner of the room. To the east of the hall is a large parlor with fireplace. To the west of the hall is a smaller dining room with fireplace. b. Second floor: The stair leads to the second floor front hall. To the west of the stair is a large bedroom with fireplace and two storage areas at the rear of the house. Two bedrooms lie to the north of the second floor front hall, while the master bedroom with fireplace is found at the end of the hall in the extreme eastern end of the structure. 2. Stairway: The mahogany stair is located in a high stair-hall which runs perpendicular to the south facade of the structure. The stair	,	The second
1. Floor plans: a. First floor: The entrance from the south side of the structure opens into a large rectangular hall with a partially enclosed stair in the northwest corner of the room. To the east of the hall is a large parlor with fireplace. To the west of the hall is a smaller dining room with fireplace. b. Second floor: The stair leads to the second floor front hall. To the west of the stair is a large bedroom with fireplace and two storage areas at the rear of the house. Two bedrooms lie to the north of the second floor front hall, while the master bedroom with fireplace is found at the end of the hall in the extreme eastern end of the structure. 2. Stairway: The mahogany stair is located in a high stair-hall which runs perpendicular to the south facade of the structure. The stair	C. Descrip	ation of Interior:
<ul> <li>a. First floor: The entrance from the south side of the structure opens into a large rectangular hall with a partially enclosed stair in the northwest corner of the room. To the east of the hall is a large parlor with fireplace. To the west of the hall is a smaller dining room with fireplace.</li> <li>b. Second floor: The stair leads to the second floor front hall. To the west of the house. Two bedrooms lie to the north of the second floor front hall, while the master bedroom with fireplace is found at the end of the hall in the extreme eastern end of the structure.</li> <li>2. Stairway: The mahogany stair is located in a high stair-hall which runs perpendicular to the south facade of the structure. The stair</li> </ul>	-	
structure opens into a large rectangular hall with a partially enclosed stair in the northwest corner of the room. To the east of the hall is a large parlor with fireplace. To the west of the hall is a smaller dining room with fireplace. b. Second floor: The stair leads to the second floor front hall. To the west of the stair is a large bedroom with fireplace and two storage areas at the rear of the house. Two bedrooms lie to the north of the second floor front hall, while the master bedroom with fireplace is found at the end of the hall in the extreme eastern end of the structure. 2. Stairway: The mahogany stair is located in a high stair-hall which runs perpendicular to the south facade of the structure. The stair		
<pre>stair in the northwest corner of the room. To the east of the hall is a large parlor with fireplace. To the west of the hall is a smaller dining room with fireplace. b. Second floor: The stair leads to the second floor front hall. To the west of the stair is a large bedroom with fireplace and two storage areas at the rear of the house. Two bedrooms lie to the north of the second floor front hall, while the master bedroom with fireplace is found at the end of the hall in the extreme eastern end of the structure. 2. Stairway: The mahogany stair is located in a high stair-hall which runs perpendicular to the south facade of the structure. The stair</pre>	structure o	
<pre>large parlor with fireplace. To the west of the hall is a smaller dining room with fireplace. b. Second floor: The stair leads to the second floor front hall. To the west of the stair is a large bedroom with fireplace and two storage areas at the rear of the house. Two bedrooms lie to the north of the second floor front hall, while the master bedroom with fireplace is found at the end of the hall in the extreme eastern end of the structure. 2. Stairway: The mahogany stair is located in a high stair-hall which runs perpendicular to the south facade of the structure. The stair</pre>		
room with fireplace. b. Second floor: The stair leads to the second floor front hall. To the west of the stair is a large bedroom with fireplace and two storage areas at the rear of the house. Two bedrooms lie to the north of the second floor front hall, while the master bedroom with fireplace is found at the end of the hall in the extreme eastern end of the structure. 2. Stairway: The mahogany stair is located in a high stair-hall which runs perpendicular to the south facade of the structure. The stair		
b. Second floor: The stair leads to the second floor front hall. To the west of the stair is a large bedroom with fireplace and two storage areas at the rear of the house. Two bedrooms lie to the north of the second floor front hall, while the master bedroom with fireplace is found at the end of the hall in the extreme eastern end of the structure. 2. Stairway: The mahogany stair is located in a high stair-hall which runs perpendicular to the south facade of the structure. The stair		
<ul> <li>hall. To the west of the stair is a large bedroom with fireplace and two storage areas at the rear of the house. Two bedrooms lie to the north of the second floor front hall, while the master bedroom with fireplace is found at the end of the hall in the extreme eastern end of the structure.</li> <li>2. Stairway: The mahogany stair is located in a high stair-hall which runs perpendicular to the south facade of the structure. The stair</li> </ul>	FOOM WICH I	
storage areas at the rear of the house. Two bedrooms lie to the north of the second floor front hall, while the master bedroom with fireplace is found at the end of the hall in the extreme eastern end of the structure. 2. Stairway: The mahogany stair is located in a high stair-hall which runs perpendicular to the south facade of the structure. The stair	ball Track	
<pre>the second floor front hall, while the master bedroom with fireplace is found at the end of the hall in the extreme eastern end of the structure. 2. Stairway: The mahogany stair is located in a high stair-hall which runs perpendicular to the south facade of the structure. The stair</pre>		
found at the end of the hall in the extreme eastern end of the structure. 2. Stairway: The mahogany stair is located in a high stair-hall which runs perpendicular to the south facade of the structure. The stair		
2. Stairway: The mahogany stair is located in a high stair-hall which runs perpendicular to the south facade of the structure. The stair		
which runs perpendicular to the south facade of the structure. The stair		
		landing at the southeast corner of the room and then continues
to rise to the second level after the landing. A simple wooden molded	to rise to	the second level after the landing. A simple wooden molded

-

Form 10-3000 (July 1969)

UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

# NATIONAL REGISTER OF HISTORIC PLACES

#### INVENTORY - NOMINATION FORM

, AIE	
Virgínia	
COUNTY	
Brunswick	
FOR NPS USE ON	LY
ENTRY NUMBER	DATE

T . T M

(Continuation Sheet)

(Number all entries)

7.

handrail, scrolled at the first floor runs broken only at the first floor landing by a round newel post. The balusters are simple wooden square members. An elaborate open stringer runs the length of the exposed stair.

3. Flooring: The floors throughout the main house are heart pine and are in excellent condition.

4. Wall and ceiling finish: The walls are all plastered with

wainscoting throughout the house. The baseboards are distinctively marbleized. 5. Doorways and doors: All doors are'cross and bible' paneled and those on the first floor have distinctive Adamesque pilastered and modillioned

architraves.

6. Windows: The windows are treated in a similar fashion to the doorways with paneled reveals and carved pilasters and architraves.

D. Site:

1. General setting and orientation: The main house and the remaining outbuildings are oriented toward the south and the bend in the Meherrin River. The approximately 40 acres overlooking the lowlands of the river form but a small part of the original estate. There are remains of a large formal garden to the north of the house with a fine stand of English boxwood near the north entrance. Another garden and an extremely large box is located several hundred feet to the south of the structure and a cemetery lies to the west of the house. Two remaining wooden outbuildings lie to the east of the mansion while a fine eighteenth century style wooden dairy stands but a few yards from the house in the same direction.

J.L.F.

PERIO	D (Check One or More as	Appropriate)			
	<ul> <li>Pre-Columbian  </li> <li>15th Century</li> </ul>	<ul> <li>D 16th Century</li> <li>17th Century</li> </ul>		) 18th Century ] 19th Century	20th Century
SPECI	FIC DATES (II Applicab	le ond Known) 1810			
AREAS	OF SIGNIFICANCE (Che Aboriginal	Eck One or More as Appropri-		litical	📋 Urban Planning
	<ul> <li>Prehistoric</li> <li>Historic</li> </ul>	Engineering Industry		ligron/Phi- losaphy	Other (Specify) <u>local history</u>
÷	Agriculture	Invention	[] Sci	ience	
	Art	🕅 Landscape Architecture		ulpture crol/Human-	
	<ul> <li>Commerce</li> <li>Communications</li> </ul>	<ul> <li>Literature</li> <li>Military</li> </ul>		itatian coter	
	Conservation	Music		ansportation	

STATEMENT OF SIGNIFICANCE

Bentfield was the home of the Joneses and the Flournoys, two prominent Southside Virginia families. The plantation's impressive brick mansion illustrates how the Federal style was adapted for the region by the local master masons and carpenters. Handsomely proportioned, the house exhibits exceptionally fine craftsmanship in its masonry and interior woodwork. Its complex of outbuildings is a rare survival and helps complete the picture of an early nineteenth century Virginia plantation.

A 1726 patent to Matthew Jones of Isle of Wight County was issued for 200 acres on the south side of the Meherrin River, south of Cattail Creek in Brunswick County. This possibly could have been in the same area where Bentfield stands today.

The first known and most famous owner of the Bentfield property was John Jones, often referred to as "Hellcat" Jones. He may have been a descendent of Matthew Jones who in 1726 patented 200 acres on the "southside of the Meherrin River, south of Cattail Creek," in the vicinity of the present house. John Jones was a Colonel during the Revolution, and a letter he wrote congratulating Governor Nelson in 1781 on the glorious victory at Yorktown is preserved in the official Virginia State Papers. John Jones served in the Virginia Senate, representing the area including Brunswick County from 1776 until 1789, and signed a petition urging the new government of Virginia to reestablish the Anglican Church in the state John Jones' son, John Jones, Jr., was born in 1764 and married Lucy Binns Cargill in 1787. It was for this son that "Hellcat" Jones built the present house on the plantation he called "Melrose", which was the first name of what later was known as "Bentfield."

Information on the Jones family in the nineteenth century is relatively scant, but Melrose remained in the possession of the Joneses until 1854 when Charles G. Jones, possibly a son of John Jones, Jr., sold the property and house referred to as the "plantation whereon I / Jones / now dwell" to George C. Rives. In this deed Jones mentions that he had inherited the property from his father, and a registery of students at the College of William and Mary shows a John N. Jones of Brunswick County registered there in 1835-36 whose guardian was a Mrs. Mary Jones. This might indicate that John Jones, Jr., was deceased by that time.

In 1859, George C. Rives, a wealthy landowner who lived at Sherwood, Albemarle County, who never actually resided at Melrose, sold this property of 720 acres for \$8,000 to Thomas Flournoy.

The property with its name changed from "Melrose" to "Bentfield" remained in the Flournoy family for 114 years. The Flournoy family dates back to Jean Jacques Flournoy, a French Hugenot who came to Virginia between 1717

Form	10-300a
(July	1969}

# C

# NATIONAL REGISTER OF HISTORIC PLACES

INVENTORY - NOMINATION FORM

STATE	
Virginia	
COUNTY	
Brunswick	
FOR NPS USE OF	NLY
ENTRY NUMBER	DATE

(Continuation Sheet)

#### (Number all entries)

8.

Thomas Flournoy, who purchased Bencfield, was originally from and 1720. Prince Edward County. A horse lover and an ardent Presbyterian, he helped establish the Union Presbyterian Church (since destroyed) in whose churchyard many of the Flournoy family are buried. The last residents of the Flournoy family to reside at Bentfield were two of Thomas Flournoy's granddaughters, both of whom were deceased by 1947.

S.P. & J.L.F.

GPO 921-724

P. MAJOR	BIBLIOGRAPHICAL	REFERENCES		8.04		and the second second	
					6-1720, Patent Book		
Bel1,	Landon, The Ol	d Free Stat	:e, 2 v	01	s., Richmond, Willi	am Byrd Press	, 1927
	Vol. I, p. 353						
			5 (1852-	-5	7) p. 277 Book 37,	(1859), p. 26	6.
	wick County Wil						
					II, pp. 261, 570.		
Child	s, James Rives, 401, 596.	Reliques d	of the l	Ri	ves, Lynchburg, 192	9, pp. 80, 11	.0, 287
King,		. A Memento	of And	ce	stors and Ancestral	Homes, Cincí	nnati.
	1890, p. 33.	/				,	
19. GEOGI	RAPHICAL DATA						
	LATITUDE AND LONGIT	TUDE COORDINA			LATITUDE AND LONG	GITUDE COORDINAT	TES
DEFIN	ING A RECTANGLE LO		Se 1993	D R		POIN I OF A PROPI	ERTY
CORNER	fra	LONGIT			LATITUDE	LONGITUD	E
	Degrees Minutes Seconds	s Degrees Minute	s Seconds		Degrees Minutes Seconds		Seconds
N.A.	36 ° 43 · 42 ·				0 , ,	° '	•
NE	36 ° 43 · 42 •						
SE SW	36 ° 43 · 23 • 36 • 43 • 23 •	77 0 52	43		•		
	MATE ACREAGE OF NO	MINATED PROP	ERTY: 20	0	2		
					PPING STATE OR COUNTY BO	DUNDARIES	
STATE:	· ····		CODE	-	OUNTY		CODE
STATE:			CODE	- 1	COUNTY:		CODE
STATE:				+			CODE
STATE:			CODE	- '	COUNTY;		CODE
STATE:			CODE	-	COUNTY:		CODE
						<u> </u>	
	PREPARED BY						
	D TITLE:						ļ
Virg	inia Historic L	andmarks Co	mnissic	n	Staff	DATE	
							1070
	inia Historic L	andmarks Co	<u>umissic</u>	m		November,	19/3
	Governor Street						,
CITY OR				Is	TATE		CODE
Rich	ond			-			51
	LIAISON OFFICER C	FRTIFICATION	1	1	Virginia NATIONAL REGIST	FR VERIFICATIO	and the second s
				1			
						,	
	designated State Liais			ł	I hereby certify that this p	orecty is included	in the
tional	Historic Preservation .	Act of 1966 (Put	olic Law		National Register.	opency 20 meredada	
89-655	). I hereby nominate th	is property for i	nclusion	ĺ	National Register.		
in the	National Register and	certify that it ha	as been	ł			
evalua	ted according to the c-	iteria and proce	dures set				
forth b	y the National Park Se	rvice. The reco	mmended		Director, Office of Archeology	and Historic Preser	vetion
level o	f significance of this	nomination is:			Director, Ottice of Archebiogy		
Na	ational 🗍 State	🖄 Local		X			
		×		H	Tube		
1	•				Dyte		
Name					ATTEST:		ļ
	R. Fishburne,						
Virgir Title	ia Historic Lar	ndmarks Com	mission	1			
-				ł			
	NOV 20 1	973			Keeper of The N	Vational Register	ł
Date	MOA GO P	<b>₩</b>			Date		
Date -							

☆ U.S. GOVERNMENT PRINTING OFFICE : 1973-729-147/1442 3-1

1

•

# NATIONAL REGISTER OF HISTORIC PLACES

INVENTORY - NOMINATION FORM

DATE

	FOR NPS USE ONL	Y
(Continuation Sheet)	ENTRY NUMBER	DATE
(Number all entries)		I
<ul> <li>9.</li> <li>Letter of Mrs. Sally T. Gerhardt, dated April 30, 19. descendent of Thomas Flournoy and was a particle descendent of Thomas Flournoy and was a particle descendent of Brunswick County, 1730-1852, communication of Brunswick County, 1730-1852, communication descendent of History and Biography, Vol. 36, <u>Virginia Magazine of History and Biography</u>, Vol. 36, <u>William and Mary Quarterly</u>, 1st Series, Vol. 19, pp Vol. 3, p. 276.</li> </ul>	rt owner of "Bentfi piled by Augusta Fo pp. 188-189.	eld"). thergill
-		
•		
	۰.,	
	G f	0 921-724

Form 10-301 (July 1969)	UNITED STATES DEPARTMENT OF THI NATIONAL PARK SERVICE	E INTERIO	DR	STATE Virgini	.a.
	NATIONAL REGISTER OF HISTOR	RIC PL.	ACES	COUNTY	
	PROPERTY MAP FORM			Brunswi	~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~
	FROFERIT MAF FORM	1		FOR NPS U	
•	(Type all entries - attach to or enclo	se with	map)	ENTRY NOMBER	T DATE
1. NAME				1	· · · · · · · · · · · · · · · · · · ·
COMMON	Bentfield				
AND/OR H	ISTORIC: Bentfield				
2. LOCATION	4				
STREET A	ND NUM BER:				
	South of Lawren	<u>cevil</u>	le off	Poute 58	
CITY OR T	FOWN:				
STATE:		CODE	COUNTY:		CODE
	Virginia		E E E E E E E E E E E E E E E E E E E	<u>Brunswick</u>	
3. MAP REPI	TKENCE				<u></u>
activez.					
SCALE:					
SCALE:					
4. REQUIREN	AENTS	·			
TOBEIN	CLUDED ON ALL MAPS				
1. Pr	operty broundaries where required.				
2. No	orth arrow.				
3. La	atitude and longitude reference.				
	UNITED STATES DEPARTMENT OF THE NATIONAL PARK SERVICE	EINTERI		STATE	
	RATIONAL FARK SERVICE			Virg	51 M 7 2

Brunswick

DATE

FOR NPS USE ONLY

ENTRY NUMBER

### NATIONAL REGISTER OF HISTORIC PLACES

## PROPERTY PHOTOGRAPH FORM

S

(Type all entries - attach to or enclose with photograph)

_	AND/OR HISTORIC:	Bentfjeld	-		
2.	LOCATION		· · · · · · · · · · · · · · · · · · ·		
	STREET AND NUMBER:	South of Law	renceville of	'f Poute 58	
	CITY OR TOWN:				
	STATE: Virg	inia	CODE COUNTY:	Brunswick	COD
3.	PHOTO REFERENCE				·····
	PHOTO CREDIT:	Zelma Lee Ov	erby, for Va.	Historic Landmarl	ks Con
	DATE OF PHOTO:	October 197			
	NEGATIVE FILED AT:				
4	IDENTIFICATION				

Form No. 10-301 Rev. 7-72	UNITED STATES DEPARTMENT OF THE NATIONAL PARK SERVICE	INTERIOR	Virginia	
	NATIONAL REGISTER OF HISTOF	IC PLACES	COUNTY	~~~~
			Brunswick	
	PROPERTY MAP FORM		FOR NPS USE	ONLY
	(Type all entries - attach to or enclo	se with map)	ENTRY NUMBER	DATE
1. NAME				
COMMON:	Bentfield			
AND/OF HIS	rosic Melrose			
2. LOCATION				
STREET AN	D NUM BER:			
<u>1 1/2 mi</u>	les Southeast of intersectio	n of Route	656 and Route 58.	
CITY OR TO	WN:	n of Route	656 and Route 58.	
Lawrenc	les Southeast of intersectio	n of Route	656 and Route 58.	
CITY OR TO	WN:	code COULT		CODE
Lawrenc	wn: eville vicinity nia	code 51 Bru		025
Lawrenc state: Virgi 3. MAP REFER	www eville vicinity nia	CODE COUNT	¥:	
Lawrenc STATE: Virgi 3. MAP REFER SOURCE:	www. eville vicinity nia ENCE	code 51 Bru	y: inswick	
Lawrenc STATE: Virgi 3. MAP REFER SOURCE: U.S.G	www. eville vicinity nia ENCE .S. 7 1/2' quadrangle White	code 51 Bru	y: inswick	
Lawrenc STATE: Virgi 3. MAP REFER SOURCE: U.S.G SCALE: 1:	www eville vicinity nia ENCE .S. 7 1/2' quadrangle White 24000	code 51 Bru	y: inswick	
CITY OR TO Lawrenc STATE: Virgi 3. MAP REFER SOURCE: U.S.G SCALE: 1: DATE: 1	<pre>www.eville vicinity nia ENCE .S. 7 1/2' quadrangle White 24000 963</pre>	CODE 51 Bru Plains, Vi	rginia	
Lawrenc STATE: Virgi 3. MAP REFER SOURCE: U.S.G SCALE: 1:	eville vicinity nia ENCE .S. 7 1/2' quadrangle White 24000 963	CODE 51 Bru Plains, Vi	rginia	
CITY OR TO Lawrenc STATE: Virgi 3. MAP REFER SOURCE: U.S.G SCALE: 1: DATE: 1 4. REQUIREME	<pre>www.eville vicinity nia ENCE .S. 7 1/2' quadrangle White 24000 963</pre>	CODE 51 Bru Plains, Vi	rginia	
CITY OR TO Lawrenc STATE: Virgi 3. MAP REFER SOURCE: U.S.G SCALE: 1: OATE: 1 4. REQUIREME TO BE INCL	www eville vicinity nia ENCE .S. 7 1/2' quadrangle White 24000 963 WTS	CODE 51 Bru Plains, Vi	rginia	
CITY OR TO Lawrenc STATE: Virgi 3. MAP REFER SOURCE: U.S.G SCALE: 1: DATE: 1 4. REQUIREME TO BE INCL I. Prop	wn: eville vicinity nia ENCE .S. 7 1/2' quadrangle White 24000 963 MTS UDED ON ALL MAPS	CODE 51 Bru Plains, Vi	rginia	

Ŷ	U.S.	GOVERNMENT	PRINTING	OFFICE :	1973-729-148/	1441 3-1
---	------	------------	----------	----------	---------------	----------

a.

orm No. 7/72)	UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE NATIONAL REGISTER OF HISTORIC PLACES PROPERTY PHOTOGRAPH FORM (Type all entries - attach to or enclose with photograph)	STATE Virginia COUNTY Brunswick FOR NPS USE ONL ENYRY NUMBER	У ОАТЕ
<u>с</u>			
Z	NAME		
0	COMMON: Bentfield AND/OR HISTORIC: Melrose		<u></u>
- 5			
- 1-	LOCATION STREET AND NUMBER: 1 1/2 miles Southeast of intersection of Route	656 and Route 38.	
C	1 1/2 miles Southeast of intersection		
n	CITY OR TOWN:		CODE
a.	Lawrenceville vicinity CODE COUNTY		025
-		inswick	1993 - 993 - 993 - 993 - 993 - 993 - 993 - 993 - 993 - 993 - 993 - 993 - 993 - 993 - 993 - 993 - 993 - 993 - 99 1993 - 993 - 993 - 993 - 993 - 993 - 993 - 993 - 993 - 993 - 993 - 993 - 993 - 993 - 993 - 993 - 993 - 993 - 993
\$		<u>an</u>	
Z	PHOTO REFERENCE PHOTO CREDIT: Virginia Historic Landmarks Commissi		
	Virginia Historic Landmarks Commission: Ric	hmond, Va.	
121	Virginia <u>Historic Landmarks Commission</u>		
ш	S A DESCRIPTION A THONE		
5	DESCRIBE VIEW, DIRECTION, ETC.		
	1. View of house from northwest.		

· ·

'orm No. 10-301a 7/72)	UNITED STATES DEPARTMENT OF NATIONAL PARK SERV	/ICE	STATE Virginia	Contraction of the second
N	ATIONAL REGISTER OF HIS	TORIC PLACES	COUNTY	
	PROPERTY PHOTOGRAPH FORM			
-				SE ONLY
C (Ty	pe all entries - attach to or enclo	se with photograph)	ENTRY NUMBER	DAT
(A) 13 4974 E			A COLUMN TO A COLUMN TO A COLUMN	
GOMMON: B				Sector Charge
AND/OR HIST	oric: Melrose			
- LUCATION		And the states of the	A REAL PROPERTY AND A REAL	
STREET AND		11111111111111111111111111111111111111	LANSIN PLANETS (	Constant Section
$\frac{1}{1/2}$ mil	es Southeast of intersec	tion of Route 6	56 and D is no	
CLTY OR TOWN	12	Last of moure o.	Jo and Route 58.	
Lawrence STATE:	eville vicinity			
- MIE		CODE COUNTY		1.00
<u> </u>	8	51 Brur	iswick	COD
Real Charles	NENCE	and the second		025
DATE OF PHOT	Virginia Historic Land	marks Commissio	in	
NEGATIVE FIL			and the second se	
				-
4 IDENTIFICATI	<u>Historic Landmarks Commi</u> ON	ssion; Richmond	Va	
DESCRIBE VI	EW, DIRECTION, ETC.		The second second second	A State Street Street
	THE DIRECTION, ETC.		and the second	10000
1 5 5	View of living room/ b			
L	7	12 U.3 50v	BRAMBUT HWATING OFFICE 1973-	729-152/1446 1
· · · ·		☆ #3 edv	ERMODUT PRAIFING OFFICE 1973-	729-15271446世-
	UNITED STATES DEPARTMENT OF TH	HE INTERIOR	STATE	729-152/1446 W-
	UNITED STATES DEPARTMENT OF TH NATIONAL PARK SERVICE	HE INTERIOR	STATE Virginia	729-152/3446 世·
		HE INTERIOR	Virginia County	729-152/1446世-
NA.	NATIONAL PARK SERVICE	HE INTERIOR E DRIC PLACES	Virgínia County Brunswick	
) NA	NATIONAL PARK SERVICE	HE INTERIOR E DRIC PLACES	STATE Virgínia County Brunswick FOR NPS USE	ONLY
) NA 1	NATIONAL PARK SERVICE	HE INTERIOR E DRIC PLACES ORM	Virgínia County Brunswick	
NA S	NATIONAL PARK SERVICE	HE INTERIOR E DRIC PLACES ORM with photograph)	STATE Virginia COUNTY Brunswick FOR NPS USE ENTRY NUMBER	ONLY
NA F (Type T: NAME	NATIONAL PARK SERVICE FIONAL REGISTER OF HISTO PROPERTY PHOTOGRAPH F all entries - attach to or enclose	HE INTERIOR E DRIC PLACES ORM with photograph)	STATE Virgínia County Brunswick FOR NPS USE	ONLY
NA F (Type NAME COMMON: Bent	NATIONAL PARK SERVICE TIONAL REGISTER OF HISTO PROPERTY PHOTOGRAPH F all entries - attach to or enclose	HE INTERIOR E DRIC PLACES ORM with photograph)	STATE Virginia COUNTY Brunswick FOR NPS USE ENTRY NUMBER	ONLY
NA F (Type	NATIONAL PARK SERVICE FIONAL REGISTER OF HISTO PROPERTY PHOTOGRAPH F all entries - attach to or enclose field field free Melrose	HE INTERIOR E DRIC PLACES ORM with photograph)	STATE Virginia COUNTY Brunswick FOR NPS USE ENTRY NUMBER	ONLY
NA (Type I. NAME COMMON: Bent AND/OR HISTOR	NATIONAL PARK SERVICE FIONAL REGISTER OF HISTO PROPERTY PHOTOGRAPH F all entries - attach to or enclose field field field	HE INTERIOR E DRIC PLACES ORM with photograph)	STATE Virginia COUNTY Brunswick FOR NPS USE ENTRY NUMBER	ONLY
NA (Type COMMON: Bent AND/OR HISTOR 2.1 LOCATION DTREET AND NO	NATIONAL PARK SERVICE FIONAL REGISTER OF HISTO ROPERTY PHOTOGRAPH F all entries - attach to or enclose field field fr. Melrose	HE INTERIOR E DRIC PLACES ORM with photograph)	STATE Virgínia County Brunswick FOR NPS USE ENTRY NUMBER	ONLY
NA (Type	NATIONAL PARK SERVICE FIONAL REGISTER OF HISTO PROPERTY PHOTOGRAPH F all entries - attach to or enclose field field field	HE INTERIOR E DRIC PLACES ORM with photograph)	STATE Virgínia County Brunswick FOR NPS USE ENTRY NUMBER	ONLY
NA (Type (Type A. NAME COMMON: Bent AND/OR HISTOR 2.1 LOCATION DTREET AND NO 1 3/2 mil CITY OR TOWN:	NATIONAL PARK SERVICE FIONAL REGISTER OF HISTO ROPERTY PHOTOGRAPH F all entries - attach to or enclose field field fr. Melrose	HE INTERIOR E DRIC PLACES ORM with photograph)	STATE Virgínia County Brunswick FOR NPS USE ENTRY NUMBER	ONLY
NA (Type (Type A. NAME COMMON: Bent AND/OR HISTOR 2.1 LOCATION DTREET AND NO 1 3/2 mil CITY OR TOWN:	NATIONAL PARK SERVICE FIONAL REGISTER OF HISTO PROPERTY PHOTOGRAPH F all entries - attach to or enclose field or Melrose MBER. cs. Southeast of intersec	HE INTERIOR E DRIC PLACES ORM with photograph)	STATE Virgínia County Brunswick FOR NPS USE ENTRY NUMBER	ONLY
NA (Type	NATIONAL PARK SERVICE FIONAL REGISTER OF HISTO PROPERTY PHOTOGRAPH F all entries - attach to or enclose field field MBER. es Southeast of intersec ville vicinity	TION OF ROUTE 6	STATE Virgínia County Brunswick FOR NPS USE ENTRY NUMBER	ONLY DATE
NA (Type	NATIONAL PARK SERVICE FIONAL REGISTER OF HISTO PROPERTY PHOTOGRAPH F all entries - attach to or enclose field or Melrose MBER. cs. Southeast of intersec	TION OF ROUTE 6	STATE Virginia COUNTY Brunswick FOR NPS USE ENTRY NUMBER	ONLY OATE CODE 025
NA	NATIONAL PARK SERVICE FIONAL REGISTER OF HISTO PROPERTY PHOTOGRAPH F all entries - attach to or enclose field field MBER. es Southeast of intersec ville vicinity	TION OF ROUTE 6	STATE Virginia COUNTY Brunswick FOR NPS USE ENTRY NUMBER S6 and Route 58.	ONLY DATE CODE 025
NA	NATIONAL PARK SERVICE FIONAL REGISTER OF HISTO PROPERTY PHOTOGRAPH F all entries - attach to or enclose field ic. Melrose MBER. es Southeast of intersec fille vicinity NCE Virginia Historic Landma	TION OF ROUTE 6	STATE Virginia COUNTY Brunswick FOR NPS USE ENTRY NUMBER S6 and Route 58.	ONLY OATE CODE 025
MA (Type	NATIONAL PARK SERVICE FIONAL REGISTER OF HISTO PROPERTY PHOTOGRAPH F all entries - attach to or enclose field ic. Melrose MBER. ics Southeast of intersec ville vicinity NCE Virginia Historic Landma 1968 D AT:	TE INTERIOR E ORIC PLACES ORM with photograph) tion of Route 6 CODE COUNTY: 51 Br Br Tks Commission	STATE Virginia County Brunswick FOR NPS USE ENTRY NUMBER 56 and Route 58.	ONLY DATE CODE 025
) NA I (Type I: NAME COMMON: Beni AND/OR HISTOR Z-LOCATION DTREET AND NO 1 3/2 mil CITY OR TOWN: LAWTENCEV STATE: Virginia DIPHOTO REPERT PHOTO CREDIT: DATE OF PHOTO NEGATIVE FILE Virginia	NATIONAL PARK SERVICE FIONAL REGISTER OF HISTO PROPERTY PHOTOGRAPH F all entries - attach to or enclose field field MEEN. es Southeast of intersec ville vicinity NCE Virginia Historic Landma 1968 O AT: Historic Landmarks Commi	RIC PLACES ORM with photograph) tion of Route 6 cove county: 51 Br rks Commission	STATE Virginia COUNTY Brunswick FOR NPS USE ENTRY NUMBER 56 and Route 58.	ONLY DATE CODE 025
) NA (Type NA Common: Bent AND/OR HISTOR AND/OR HISTOR DIRECT AND NO 1 1/2 mil CITY OR TOWN: LAWTENCE STATE: Virginia DATE OF PHOTO NEGATIVE FILE Virginia	NATIONAL PARK SERVICE FIONAL REGISTER OF HISTO PROPERTY PHOTOGRAPH F all entries - attach to or enclose field field or Melrose MBER. es Southeast of intersec ville vicinity NCE Virginia Historic Landma 1968 DAT: Historic Landmarks Commine N	RIC PLACES ORM with photograph) tion of Route 6 cove county: 51 Br rks Commission	STATE Virginia COUNTY Brunswick FOR NPS USE ENTRY NUMBER 56 and Route 58.	ONLY DATE CODE 025
) NA (Type NA Common: Bent AND/OR HISTOR AND/OR HISTOR DIRECT AND NO 1 1/2 mil CITY OR TOWN: LAWTENCE STATE: Virginia DATE OF PHOTO NEGATIVE FILE Virginia	NATIONAL PARK SERVICE FIONAL REGISTER OF HISTO PROPERTY PHOTOGRAPH F all entries - attach to or enclose field field MEEN. es Southeast of intersec ville vicinity NCE Virginia Historic Landma 1968 O AT: Historic Landmarks Commi	RIC PLACES ORM with photograph) tion of Route 6 cove county: 51 Br rks Commission	STATE Virginia COUNTY Brunswick FOR NPS USE ENTRY NUMBER 56 and Route 58.	ONLY DATE CODE 025
I. NAME COMMON: Bent AND/OR HISTOR 2. LOCATION DTREET AND NO 1 3/2 mil CITY OR TOWN: LAWTENCEV STATE: Virginia J. PHOTO REFERE PHOTO CREDIT: DATE OF PHOTO NEGATIVE FILE Virginia	NATIONAL PARK SERVICE FIONAL REGISTER OF HISTO PROPERTY PHOTOGRAPH F all entries - attach to or enclose field field or Melrose MBER. es Southeast of intersec ville vicinity NCE Virginia Historic Landma 1968 DAT: Historic Landmarks Commine N	RIC PLACES ORM with photograph) tion of Route 6 cove county: 51 Br rks Commission	STATE Virginia COUNTY Brunswick FOR NPS USE ENTRY NUMBER 56 and Route 58.	ONLY DATE CODE 025
NA	NATIONAL PARK SERVICE FIONAL REGISTER OF HISTO PROPERTY PHOTOGRAPH F all entries - attach to or enclose field field or Melrose MBER. es Southeast of intersec ville vicinity NCE Virginia Historic Landma 1968 DAT: Historic Landmarks Commine N	HE INTERIOR ENTERIOR WIC PLACES ORM with photograph) tion of Route 6 code county: 51 Br rks Commission ssion: Richmond	STATE Virginia COUNTY Brunswick FOR NPS USE ENTRY NUMBER 56 and Route 58.	ONLY DATE CODE 025

1

